



August 25, 1997

Food and Drug Administration
Seattle District
Pacific Region
22201 23rd Drive S.E.
P.O. Box 3012
Bothell WA 98041-3012

Telephone: 206-486-8788 Fax: 206-483-4996

VIA FEDERAL EXPRESS

In reply refer to Warning Letter SEA 97-26

Karen Rochelle, M.D.
Medical Director
Radiology Associates, Inc., P.S.
3822 Colby Avenue
Everett, Washington 98201

WARNING LETTER

Dear Dr. Rochelle:

Your facility was inspected on August 20, 1997, (inspection ID 1325970003) by a representative of the State of Washington radiation control program, acting on behalf of the Food and Drug Administration (FDA). This inspection revealed that your facility failed to comply with certain of the Quality Standards for Mammography (Standards) as specified in Title 21, Code of Federal Regulations (CFR), Part 900.12, as follows:

- 1. The interpreting physician did not meet the requirement of being board certified by any of the approved boards or having two months full-time training in the interpretation of mammograms:
- 2. The interpreting physician did not meet the requirement of being board certified by any of the approved boards or having two months full-time training in the interpretation of mammograms:

The specific deficiency noted above appeared under the Level 1 heading on your MQSA Facility Inspection Report, which was issued at the close of the inspection.

In addition, your response should address the Level 2 noncompliances that were listed on the inspection report provided to you at the close of the inspection. These Level 2 noncompliances are:

3. The interpreting physician did not meet the continuing experience requirement of having read and interpreted mammograms from an average of 40 patient examinations per months over 24 months:

Karen Rochelle, M.D. Radiology Associates, Inc., Everett, WA Re: Warning Letter SEA 97-26 Page 2

- 4. The interpreting physician did not meet the continuing experience requirement of having read and interpreted mammograms from an average of 40 patient examinations per months over 24 months:
- 5. The interpreting physician did not meet the continuing experience requirement of having read and interpreted mammograms from an average of 40 patient examinations per month over 24 months:
- 6. The interpreting physician did not meet the initial training requirement of having 40 hours of continuing medical education in mammography:
- 7. The interpreting physician did not meet the initial training requirement of having 40 hours of continuing medical education in mammography:
- 8. The interpreting physician did not meet the requirement of having read and interpreted mammograms from the examinations of at least 240 patients in 6 months:
- 9. The interpreting physician did not meet the requirement of having read and interpreted mammograms from the examinations of at least 240 patients in 6 months:

This letter is not intended to be an all-inclusive list of deficiencies at your facility. It is your responsibility to ensure adherence to each requirement of the Mammography Quality Standards Act of 1992 and regulations under the Act. The specific violation noted in this letter and in the printed summary of test results and the inspection observations issued at the close of the inspection may be symptomatic of serious underlying problems in your facility's quality assurance program for mammography. You are responsible for investigating and determining the causes of the violations from the quality standards.

You should take prompt action to correct these deficiencies. Failure to promptly correct these violations may result in regulatory action being initiated by the FDA without further notice. A facility may be subject to civil money penalties up to \$10,000 for each failure to substantially comply with the Standards. A facility may also have its certificate suspended or revoked for failure to comply with the Standards. Continuation of any activity related to the provision of mammography by a facility

Karen Rochelle, M.D. Radiology Associates, Inc., Everett, WA Re: Warning Letter SEA 97-26 Page 3

that constitutes a serious risk to human health may result in injunction.

You should be advised that FDA regulations do not prevent enforcement of requirements under State laws and regulations. In some cases, State requirements may be more stringent than requirements under FDA regulations. You may receive a letter or notification from the State advising you of this fact. When conducting corrective action, you should take into consideration the more stringent State requirements, if any.

Please notify this office in writing within fifteen (15) working days of receipt of this letter, of the specific steps you have taken to correct the noted violations, including an explanation of each step being taken to prevent the recurrence of similar violations. In your response, you must also respond to the items on your printout. If corrective action cannot be completed within 15 working days, state the reason for the delay and the time within which corrections will be completed. If your response includes equipment test results, please include equipment -settings (including technique factors), raw test data, and calculated final results, where appropriate. If the noncompliances found relate to quality control or other records, example records showing complaint record keeping should be included with your submission (patient names or identification should be omitted from any copies submitted).

Please send the original copy of your response to Richard S. Andros, Compliance Officer, Food and Drug Administration, at the above address. Also, send a copy to the State radiation control office that conducted the inspection referenced in this letter.

Sincerely,

District Director

Seattle District Office

cc: Bill Van Pelt
X-ray Control
WA State Dept of Health
2409 East Valley
Seattle, Washington 98112